

Transformer Regasketing Expertise

MAINTAIN TRANSFORMER INTEGRITY & ENVIRONMENTAL RESPONSIBILITY

SPX Transformer Solutions can help solve leakage problems on any manufacturer's medium to large power transformers. We can repair specific leaks or completely regasket all transformer openings and reprocess the oil to help restore equipment to peak operating condition.



WHY REGASKET YOUR TRANSFORMER

- Oil contamination of the surrounding ground and ground water can require expensive environmental cleanup procedures.
- Moisture and oxygen can enter a transformer through leaking gaskets, causing accelerated aging and/or failure of insulation.
- Moisture in oil results in lower dielectric strength, leading to increased risk of transformer failure.
- High moisture content in oil also reduces transformer overload capability.
- Leaks in the nitrogen blanketed air space above the oil allow nitrogen to escape, causing more frequent bottle replacement and alarm issues when provided with a positive pressure system.


WHY USE SPX TRANSFORMER SOLUTIONS FOR LEAK REPAIR AND REGASKETING REQUIREMENTS

- Nationwide coverage
- Ability to supply any type of gasket required:
 - Original gasket kits for many of our own transformers
 - Field cut gaskets for any size opening on other manufacturers' transformers
- Use our own equipment and oil processing rigs to remove moisture after regasketing is performed
- Provide welding repairs for tank and/or piping cracks
- Offer replacement of any accessories found to be defective, such as gauges, dresser couplings, conservator bags and bushings
- Our crew performs complete pre- and post-electrical testing



ADDITIONAL SERVICES

In addition to regasketing, SPX Transformer Solutions possesses the equipment, experience and capabilities to complete other repairs and/or upgrades you may elect to perform while your transformer is deenergized. These services include insulation dryouts, bushing replacements, LTC repairs/upgrades, preventative and corrective maintenance as well as component replacement and internal inspections, including condition assessments, to ensure the most value for your outage dollar. Our highly trained technicians offer years of industry experience and an outstanding field service record for professional handling of all your service needs.



CALL 800-758-4384

VISIT www.waukeshaservice.com

SPX TRANSFORMER SOLUTIONS

2701 US Hwy 117 South | Goldsboro, North Carolina 27530

Emergency Service Available 24/7/365: 888-365-24x7